

ZOXDEAL EXCLUSIVE BONUS

Electric Screwdriver Battery & Care Guide

Small cordless drivers die early when they are charged wrong and stored empty. Five habits keep the HOTO's 1,500 mAh battery and S2 bits working for years.

Charge before the first job, not after unboxing forever.

The kit ships without a charging cable. Any USB-C cable and phone charger works. A full charge takes up to 150 minutes, and the driver cannot run while charging - so charge the night before a build day.

Do not store it empty.

Lithium batteries age fastest flat. If the driver will sit for a month, leave it around half charged and top it up every few months.

Let manual mode do the heavy work.

The motor gives 4 Nm; your hand gives 8 Nm through the same driver. Break stubborn screws loose by hand first, then spin them out electrically. The battery and the gears both last longer.

Stop when it stalls.

Holding the trigger on a stalled screw cooks the motor and drains the pack. Two stalls on the same screw means switch torque setting or switch to manual.

Keep bits dry and in the case.

S2 steel is hard (60 HRC) but it can still spot-rust in a damp garage. The magnetic-lid case keeps the set together - use it instead of a drawer.

Match bits exactly.

A near-fit bit wobbles and rounds both itself and the screw. The kit's slight bit play makes exact matches matter more, not less.

Free bonus from ZoxDeal — zoxdeal.com. Based on the manufacturer manual and verified owner reports, October 2026.